



Popcorn Machine

Keep motor and heat switch “off” when not popping corn

Keep doors open when popping corn. Keep doors closed when you are not popping corn.

6 easy Steps to Pop the Best Popcorn:

1. Turn all switches “ON”
2. For first batch only let the kettle heat about 4 minutes
3. Add oil or oil bar, then cup of corn with FLAVACOL in it.
4. Dump when popping is about 99% completed.
5. Repeat step 3 and step 4- Always pop at least 5 batches each time you pop.
6. (On final batch only) Turn the kettle heat switch OFF as soon as corn starts popping rapidly (to raise kettle lid)

Warning! Keep kettle switch “OFF” when not popping